

# CNT Motion Series 1000 Router History

## 4<sup>th</sup> Owner - *Purchased In 2013*

- Original Owner Purchased In 2004 and Used Very Little
- Second Owner Purchased In 2010
  - ✓ Second Owner Sent Back To CNCT Motion for  
Operational Inspection and Computer Software Upgrade  
Before Delivery To Their Facility
  - ✓ Second Owner Used Very Little
- Third Owner Purchased in ~2012 and *Never Installed Router*
  - ✓ Remained In Warehouse
  - ✓ Never Connected to Electrical Service

# CNT Motion Series 1000 Router


## Issues:

- Machine 'Gets Lost' in X When Running a Program
- The Longer the Program (More Lines of G-Code), The More 'Error'
- Cumulative Error is Always in the 'X+' Direction
- Error Also Seems to be a Function of 'X' Distance From  
Either Machine Zero ('Home'/G28) or Local Zero,  
Depending Upon Whether In G90 or G92 Mode
- This Error First Manifested Itself When I Started Running Programs
  - Tool Change Positions Were The First Indication Of an Error
  - When I Began Machining Rigid Urethane Foam, the Machine  
Showed Similar Error
- If Running In Manual Mode, Tool Changes Are **ALWAYS** Accurate

# Problem Statement

- 1) CNT Motion Router With WinCNC Control Software Loses Position In 'X'
- 2) The 'X' Error Is Realized:
  - a) During The Execution Of The Program
  - b) At Tool Change
- 3) The Error Appears To Be Cumulative
- 4) The Error Appears To Be A Function Of The Position Of Either  
The Local Zero, Machine Zero, or Both -- ***Don't Know!***

# CNT Motion CNC Router




26 July 2015

Mid-Continent Composites

4




# Test Block #1 Solid Model




Plan-view



# The Computer/WinCNC Viewer Screen Shows Proper Execution of the Program




## Test Block #1 During Roughing




Does **NOT** Match WinCNC Viewer Image of Test Block #1!!!

## Test Block #1 During Roughing







## Tool #3



Tool #3 Spindle  
Position After ~1K  
G-Code Lines Executed  
(Mostly X-Y-Z Moves)




Tool #3 Spindle  
Position After ~50K  
G-Code Lines Executed  
(Mostly X-Y-Z Moves)




Tool #3 Spindle  
Position After Fresh  
G28/'HOME'  
(**NO Programmed** X-Y-Z Moves  
After G28)


## Tool #4



Tool #4 Spindle  
Position After ~1K  
G-Code Lines Executed  
(*Mostly X-Y-Z Moves*)




Tool #4 Spindle  
Position After ~50K  
G-Code Line Executed  
(*Mostly X-Y-Z Moves*)




Tool #4 Spindle  
Position After Fresh  
G28/'HOME'  
(**NO Programmed** X-Y-Z Moves  
After G28)

## Tool #5




Error  
(*Est.*)

Tool #5 Spindle  
Position After ~1K  
G-Code Lines Executed  
(*Mostly X-Y-Z Moves*)



Error

Tool #5 Spindle  
Position After ~50K  
G-Code Line Executed  
(*Mostly X-Y-Z Moves*)




No Error


Tool #5 Spindle  
Position After Fresh  
G28/'HOME'  
(**NO Programmed** X-Y-Z Moves  
After G28)




## Tool #6



Tool #6 Spindle  
Position After ~1K  
G-Code Lines Executed  
(*Mostly X-Y-Z Moves*)




Tool #6 Spindle  
Position After ~50K  
G-Code Line Executed  
(*Mostly X-Y-Z Moves*)




Tool #6 Spindle  
Position After Fresh  
G28/'HOME'  
(**NO Programmed** X-Y-Z Moves  
After G28)


## Tool #7



Tool #7 Spindle  
Position After ~1K  
G-Code Lines Executed  
(Mostly X-Y-Z Moves)



Tool #7 Spindle  
Position After ~50K  
G-Code Line Executed\*  
(Mostly X-Y-Z Moves)



Tool #7 Spindle  
Position After Fresh  
G28/'HOME'  
(**NO Programmed** X-Y-Z Moves  
After G28)

***Any Ideas?***

***Any Solutions??***

***Thanks To All Who Have Helped!***

***I Appreciate All Your Inputs,  
Comments, and Suggestions!!***